S0=D0^DC

S1=D1^S0^TC^DC

S2=D2^S1^TC^DC

S3=D3^S2^TC^DC

S4=D4^S3^TC^DC

S5=D5^S4^TC^DC

S6=D6^S5^TC^DC

S7=D7^S6^TC^DC

S8=TC^1

S9=DC

# Figure 1

 $S0=D0^NNV$ 

S1=D1^S0^INV

S2=D2^S1^INV

S3=D3^S2^INV

S4=D4^S3^INV

S5=D5^S4^INV

S6=D6^S5^INV

S7=D7^S6^INV

S8=1

S9=INV

## Figure 2

#### S0=D0^DC

S1=D1^S0^AUX^DC

S2=D2^S1^AUX^DC

S3=D3^S2^AUX^DC

S4=D4^S3^AUX^DC

S5=D5^S4^AUX^DC

S6=D6^S5^AUX^DC

S7=D7^S6^AUX^DC

S8=AUX^1

S9=DC

# Figure 3

S0=D0^INV

S1=D1^S0^INV

S2=D2^S1^INV

S3=D3^S2^INV

S4=D4^S3^INV

S5=D5^S4^INV

S6=D6^S5^INV

S7=D7^S6^INV

S8=AUX

S9=INV

## Figure 4